

Work Order ID 86459

June-29-12 12:41:20 PM

Slip Tues 07/07

86459

Page 1

Item ID: D412-704-045

Accept

N900040100

Setup Start *NS1*

Revision ID:

Item Name: Cable Assembly (212/214/412) 3

Stop *NS2*

Start Date: 6/29/12 Start Qty: 1.00

4

Cust Item ID:

Required Date: 7/03/12 Req'd Qty: 4.00

4

Customer:

Reference:

Approvals:

Process Plan:

Date:

Tooling:

Date:

QC:

Date:

SPC (Y/N):

Date:

Run Start *NR1*

Stop *NR2*

Sequence ID/
Work Center ID

Operation
Description

Set Up/
Run Hours

Tool ID

Tool #

Plan
Code

Accept
Qty

Reject
Qty

Reject
Number

Insp.
Stamp

Draw Nbr

Revision Nbr

DSI9611

A

IIN D412-704

C

100

0.00

100

Small Fab

Small Fab

Memo

0.00

Small Fab

Assemble as per dwg

32 0

9/12/07/03

110

QC5- Inspect part completeness to step on W/O

0.00

110

QC

Memo

0.00

Quality Control

5/12/13

73

Picklist Print

June-29-12 12:41:19 PM

Page 1

Work Order ID: 86459

Parent Item: D412-704-045

Parent Item Name: Cable Assembly (212/214/412)

Start Date: 6/29/12

Required Date: 7/03/12

Start Qty: 4.00

Required Qty: 4.00

Comments: IPP Rev:B05.01.28 Added Figures 1-2KJ/RF
IPP Rev:C 08-10-08 as per revB DD verified by:EC
9611 DD verf:EC
IPP REV:D 12.05.10 per DSI

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
AN3-10A Bolt		Purchased	No			100	Each	125.0000	1	4		6/29/12	
				<u>Location</u>		<u>Loc Qty</u>		<u>Loc Code</u>					
				GA		8							
				119084		8				3			
				ST351		117							
				117795		2							
				120873		115							
AN3-5A Bolt		Purchased	No			100	Each	802.0000	1	4		6/29/12	
				<u>Location</u>		<u>Loc Qty</u>		<u>Loc Code</u>					
				ST350		802							
				115371		46							
				117423		124				3			
				119355		200							
				120187		426							
				121185		6							
AN960JD10 Washer	NAS1149D0363J	Purchased	No			100	Each	0.0000	2	8		6/29/12	
				40 M120644									
AN960JD10L Washer	NAS1149D0332J	Purchased	No			100	Each	0.0000	2	8		6/29/12	
				40 M119717									
D3217-3 Cable 80.5"		Manufactured	No			100	Each	12.0000	1	4		6/29/12	
				<u>Location</u>		<u>Loc Qty</u>		<u>Loc Code</u>					
				ST223		12							
				79806		1							
				83195		1							
				84429		10				3			

Picklist Print

June-29-12 12:41:19 PM

Page 2

Work Order ID: 86459

Parent Item: D412-704-045

Parent Item Name: Cable Assembly (212/214/412)

Start Date: 6/29/12

Required Date: 7/03/12

Start Qty: 4.00

Required Qty: 4.00

D3257-1 Manufactured No 100 Each 3.0000 1 4

Fitting

Location Loc Qty Loc Code

ST035 3

83196 3

D3258-1 Manufactured No 100 Each 7.0000 1 4

Angle Bracket

Location Loc Qty Loc Code

ST035 7

76165 7

MS21042L3 Purchased No 100 Each 3,423.0000 2 8

Nut

Location Loc Qty Loc Code

ST300 1423

117885 32

119017 777

119075 138

121444 476

ST317 2000

122141 2000

NAS509-3 Purchased No 100 Each 48.0000 3 12

Nut

Location Loc Qty Loc Code

ST280 48

118384 12

121827 36

June-29-12 12:41:19 PM

Shop Packet Print

Page 2




FIGURE 4 – Detail B. View looking Aft (Pilot's Side)
(-011/-013/-015 Installations)




FIGURE 5 – Detail L.

DART SERVICE INSTRUCTION

TO AMEND IIN-D412-704 REV. C OR EARLIER

AND ICA-D412-704 REV. 4 OR EARLIER

REF CANADIAN STC SH93-34

REF FAA STC SR00957NY

REF EASA STC EASA.IM.R.00696

PURPOSE

The purpose of this Dart Service Instruction is to correct part number error in Installations Instruction IIN-D412-704 Rev. C or earlier and Instructions for Continued Airworthiness ICA-D412-704 Rev. 4 or earlier. The AN3-13A bolt should be replaced with an AN3-10A bolt in Figure 5 - Detail L in IIN-D412-704 and Figure 25-4 Detail L in ICA-D412-704. See sheet 2.

PART LIST CORRECTION

Revise Part Lists in IIN-D412-704 & ICA-D412-704 as follows:

NOW

Qty -043	Qty -045	Part Number	Description
X		D205-704-043	CABLE ASSEMBLY (205)
	X	D412-704-045	CABLE ASSEMBLY (210/212/214/412)
1	1	AN3-10A	BOLT

WAS




Qty -043	Qty -045	Part Number	Description
X		D205-704-043	CABLE ASSEMBLY (205)
	X	D412-704-045	CABLE ASSEMBLY (210/212/214/412)
1	1	AN3-13A	BOLT

CANADA
DEPARTMENT OF TRANSPORT
AIRCRAFT CERTIFICATION
BRANCH
DAO # 01-O-01

APPROVED

BY: 
D. SHEPHERD (DE # 02)


DATE: 12.05.07
CERT. NO.: SH93-34
ISSUE NO.: 2

A	NEW ISSUE (REF PAR	RF	12.05.07
REV.	DESCRIPTION	BY	DATE
DESIGN	RF	DART AEROSPACE LTD	
DRAWN	RF	HAWKESBURY, ONTARIO, CANADA	
CHECKED		DRAWING NO.	REV. A
MFG. APPR.	N/A	DSI 9611	SHEET 1 OF 2
APPROVED		TITLE	SCALE
DE APPR.		PART NUMBER CORRECTION NTS	
DATE	12.05.07	COPYRIGHT © 2012 BY DART AEROSPACE LTD THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.	

FIGURES CORRECTION

Revise Detail L Figure 5 of IIN-D412-704 and Detail L Figure 25-4 of ICA-D412-704 as follows:

NOW



WAS




Figure 5 - Detail L or Figure 25-4 - Detail L

CANADA
DEPARTMENT OF TRANSPORT
AIRCRAFT CERTIFICATION
BRANCH
DAO # 01-O-01

APPROVED

BY: *[Signature]*
D. SHEPHERD (DE # 02)

DATE: 12.05.07
CERT. NO.: SH93-34
ISSUE NO.: 2

DESIGN	RF	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	
DRAWN	RF		
CHECKED	RF	DRAWING NO.	REV. A
MFG. APPR.	N/A	DSI 9611	SHEET 2 OF 2
APPROVED	RF	TITLE	SCALE
DE APPR.	RF	PART NUMBER CORRECTION NTS	
DATE	12.05.07	COPYRIGHT © 2012 BY DART AEROSPACE LTD THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.	